# North Stonington Center for Emergency Services - Field Report #8 - 9-18-17 - 9-22-17

Prepared by Michael Faenza

### **Description**

This field report contains observations from site activities performed during the week of September 22, 2017.

The purpose of this report is to document the progress of the project.

Subcontractors working on site this week: Suchocki & Son Inc. - Sitework Black Dog Concrete - Concrete Main Enterprises - Plumbing

Key Activities this week include: Installation of Fire Protection Wet Well Structure - Complete Backfill of Wet Well Excavation - In Progress Installation of Storm Water Management System - In Progress Forming and Pouring of Tie, Beams, Foundation Walls and Impact Walls - In Progress Installation of Underground Sanitary and Grease Waste Piping - In Progress


Please see individual photos and locations within the report for specific detail of activities performed.

#### **Contents**

#53 September	19th .	 						 						 				3
#54 September	19th .	 						 						 				3
#55 September	19th .	 																4
#56 September	20th .	 																5
#57 September	20th .	 	•					 										6
#58 September	21st .	 																7
#59 September	21st .	 	•					 										8
#60 September	21st .	 	•					 										9
#61 September	21st .	 						 										10
#62 September	21st .	 						 						 				11

#### **North Stonington Emergency Services Building**

## #53 September 19th



**Sheet** C2

#### **Description**

Wet well has arrived and been dropped into pit.

#### **Photos**



Sep 19, 2017 at 10:02am

### Status

Open


#### Created

Sep 19, 2017 at 10:02am mfaenza@crec.org

#### **Last Updated**

Sep 19, 2017 at 3:15pm

## **#54 September 19th**



Sheet P100

### Status

Open

#### Created

Sep 19, 2017 at 3:15pm mfaenza@crec.org

#### **Last Updated**

Sep 19, 2017 at 3:16pm


## Description

Underground plumbing installation has commenced.



Sep 19, 2017 at 3:16pm

## #55 September 19th



**Sheet** S100

## **Description** Foundation wall has been backfilled.

**Status** Open

Created
Sep 19, 2017 at 3:17pm
mfaenza@crec.org

**Last Updated** Sep 19, 2017 at 3:19pm



Sep 19, 2017 at 3:18pm

## **#56 September 20th**



**Sheet** C2

## **Description**Wet well has been connected and is being tested with water.

**Status** Open

Created Sep 20, 2017 at 3:13pm mfaenza@crec.org

**Last Updated** Sep 20, 2017 at 3:15pm




Sep 20, 2017 at 3:14pm



Sep 20, 2017 at 3:14pm

## #57 September 20th



Sheet S100

**Description**Foundation walls and piers have been formed at apparatus bay doors.

**Status** Open


Created Sep 20, 2017 at 3:16pm mfaenza@crec.org

**Last Updated** Sep 21, 2017 at 2:58pm



Sep 20, 2017 at 3:16pm

## **#58 September 21st**



**Sheet** S100

## **Description** Tie beams have been poured.

**Status** Open


Created Sep 21, 2017 at 2:58pm mfaenza@crec.org

**Last Updated** Sep 21, 2017 at 2:59pm



Sep 21, 2017 at 2:59pm

## **#59 September 21st**



**Sheet** S100

## **Description**Foundation wall and impact walls have been poured.

**Status** Open


Created Sep 21, 2017 at 2:59pm mfaenza@crec.org

**Last Updated** Sep 21, 2017 at 3:00pm



Sep 21, 2017 at 2:59pm

## #60 September 21st



**Description**Wet well has been partially backfilled.

**Status** Open

Sheet

C2


Created Sep 21, 2017 at 3:00pm mfaenza@crec.org

Last Updated Sep 21, 2017 at 3:02pm



Sep 21, 2017 at 3:01pm

## #61 September 21st



Sheet C3

# **Description**Stormwater inlet structure has been installed and tied into Stormwater management system.

**Status** Open


Created Sep 21, 2017 at 3:02pm mfaenza@crec.org

**Last Updated** Sep 21, 2017 at 3:03pm



Sep 21, 2017 at 3:03pm

## #62 September 21st



**Description**Grease interceptor piping in progress.

Sheet P100 **Status** Open


Created Sep 21, 2017 at 3:05pm mfaenza@crec.org

**Last Updated** Sep 21, 2017 at 3:05pm



Sep 21, 2017 at 3:05pm

## #63 September 21st



**Description**Underground piping has been stubbed up.

**Sheet** P100

**Status** Open

Created Sep 21, 2017 at 3:06pm mfaenza@crec.org

**Last Updated** Sep 21, 2017 at 3:06pm

### **North Stonington Emergency Services Building**

#### **Photos**



Sep 21, 2017 at 3:06pm