



Center for Emergency Services North Stonington

40 Main Street
North Stonington, Connecticut 06359
(860) 535-2877
Fire.EMS.comm@nsvfc.org



3 Bay Walk-Through Notes January 30, 2020 2 10:32 AM

In attendance:

Committee: Chairman Carl Johnston, Bob Shabunia.

Others: First Selectman Mike Uργο, Admin. /Finance Director Christine Dias

Committee Secretary Kati Murphy

Tim Bartha of Suchocki & Son and Steve June of SP&A

Walk-through was positive. No major issues. Chief Steinhart had emailed a few concerns prior to the meeting and Bob and Carl questioned stone and bank stabilization at the back of the building

Combo lock needed at entry door.

Town to contact their locksmith for new lock.

Light over entry door not working.

Tim Bartha to follow-up

Fire extinguisher cabinet installed upside down and door needs to have glass, not plastic.

Tim Bartha was ordering glass after the walk-through. Cabinet now properly installed.

Regarding stone and bank stabilization, Tim Bartha stated that in the spring they would come back and place 2ft of 2in stone along the back of the building and take measures to stabilize the bank once it is warm enough for vegetation to grow.

Walk-through completed at 10:45 AM