

North Stonington Center for Emergency Services - Field Report #10 - 10-2-17 - 10-6-17

Prepared by Michael Faenza

Description

This field report contains observations from site activities performed during the week of October 6, 2017.

The purpose of this report is to document the progress of the project.

Subcontractors working on site this week:

Suchocki & Son Inc. - Sitework
Black Dog Concrete - Concrete
Main Enterprises - Plumbing
CE Electrical - Electrical

Key Activities this week include:

Installation Fire Protection Storage Tank - Complete
Backfill of Fire Protection Storage Tank - In Progress
Forming and Pouring of Tie, Beams, Foundation Walls and Impact Walls - In Progress
Installation of Underslab Electrical Conduit - In Progress
Backfilling of Building Interior Slabs - In Progress

Please see individual photos and locations within the report for specific detail of activities performed.


Contents

#78 October 4th	3
#79 October 4th	4
#80 October 4th	5
#81 October 4th	6
#82 October 4th	7
#83 October 5th	7
#84 October 5th	8
#85 October 6th	9
#86 October 6th	10

North Stonington Emergency Services Building

#87 October 6th	11
#88 October 6th	12
#89 October 6th	13

#78 October 4th



Sheet
P100

Status
Open

Created
Oct 4, 2017 at 10:32am
mfaenza@crec.org

Last Updated
Oct 4, 2017 at 10:33am

Description


Underground piping in progress.

Photos



Oct 4, 2017 at 10:33am

#79 October 4th



Sheet
S100

Status
Open

Created
Oct 4, 2017 at 10:33am
mfaenza@crec.org

Last Updated
Oct 4, 2017 at 10:34am

Description


Backfill of administration area is nearly complete and has been compacted.

Photos



Oct 4, 2017 at 10:34am

#80 October 4th



Sheet
S100

Status
Open

Created
Oct 4, 2017 at 10:34am
mfaenza@crec.org

Last Updated
Oct 4, 2017 at 10:35am

Description


Foundation walls and impact walls have been poured.

Photos



Oct 4, 2017 at 10:35am

#81 October 4th



Sheet C3

Status Open

Created Oct 4, 2017 at 10:35am
mfaenza@crec.org

Last Updated Oct 4, 2017 at 10:36am

Description


Fire protection storage tank has been delivered, installed and is being back filled.

Photos



Oct 4, 2017 at 10:36am

#82 October 4th



Sheet C3

Status Open

Created Oct 4, 2017 at 10:37am mfaenza@crec.org

Last Updated Oct 5, 2017 at 3:01pm

Description


Leaching galleries have been delivered for septic system.

Photos



Oct 4, 2017 at 10:37am

#83 October 5th



Sheet E201

Status Open

Created Oct 5, 2017 at 3:16pm mfaenza@crec.org

Last Updated Oct 5, 2017 at 3:16pm

Description

Underground electrical installation in main electrical room underslab.


North Stonington Emergency Services Building

Photos



Oct 5, 2017 at 3:16pm

#84 October 5th



Sheet
C3

Status
Open

Created
Oct 5, 2017 at 3:17pm
mfaenza@crec.org

Last Updated
Oct 5, 2017 at 3:17pm

Description

Fire protection tank backfill in progress.


North Stonington Emergency Services Building

Photos



Oct 5, 2017 at 3:17pm

#85 October 6th



Sheet
C3

Status
Open

Created
Oct 6, 2017 at 12:58pm
mfaenza@crec.org

Last Updated
Oct 6, 2017 at 1:07pm

Description


Fire protection storage tank back fill in progress.

Photos



Oct 6, 2017 at 12:59pm

#86 October 6th



Sheet
E201

Status
Open

Created
Oct 6, 2017 at 1:07pm
mfaenza@crec.org

Last Updated
Oct 6, 2017 at 1:09pm

Description

Electrical conduit installation is nearly complete in electrical room area.

North Stonington Emergency Services Building

Photos




Oct 6, 2017 at 1:08pm



Oct 6, 2017 at 1:09pm

#87 October 6th



Sheet
S100

Status
Open

Created
Oct 6, 2017 at 1:09pm
mfaenza@crec.org

Last Updated
Oct 6, 2017 at 2:17pm

Description


Piers have been formed.

Photos



Oct 6, 2017 at 1:09pm

#88 October 6th



Sheet
S100

Status
Open

Created
Oct 6, 2017 at 2:17pm
mfaenza@crec.org

Last Updated
Oct 6, 2017 at 2:18pm

Description
Concrete is being poured.


North Stonington Emergency Services Building

Photos



Oct 6, 2017 at 2:18pm

#89 October 6th



Sheet
S100

Status
Open

Created
Oct 6, 2017 at 3:07pm
mfaenza@crec.org

Last Updated
Oct 6, 2017 at 3:08pm

Description

Tie beam is being poured.

Photos



Oct 6, 2017 at 3:07pm