

North Stonington Center for Emergency Services - Field Report #20 - 12-11-17 - 12-22-17

Prepared by Michael Faenza

Description

This field report contains observations from site activities performed during the week of December 15, 2017 and December 22, 2017.

The purpose of this report is to document the progress of the project.

Subcontractors working on site these weeks:

- Suchocki & Son Inc. - Sitework
- Xenelis Construction - Pre-Engineered Building
- East Coast Wall System - Masonry
- MCM Acoustics LLC - Framing & Drywall
- Depco Mechanical - HVAC
- CE Electric - Electrical
- Black Dog Concrete - Concrete

Key Activities this week include:

- Erection of Steel for Pre-Engineered Building - In Progress
- Installation of Building Wall Panels - In Progress
- Installation of Interior CMU Wall -Complete
- Installation of Decon Tank - In Progress
- Installation of Apparatus Bay Door Concrete Infills - In Progress
- Installation of Radio Tower Base - In Progress
- Interior Metal Framing - In Progress
- Installation of Hangars for HVAC Ductwork in Admin Area - In Progress

Please see individual photos and locations within the report for specific detail of activities performed.

Contents


#180 December 14th	3
#181 December 14th	4
#182 December 14th	5
#183 December 19th	6
#184 December 19th	7

North Stonington Emergency Services Building

#185 December 19th	8
#186 December 19th	9
#187 December 19th	10
#189 December 21st	11
#191 December 22nd	12
#192 December 22nd	13
#193 December 22nd	14

North Stonington Emergency Services Building

#180 December 14th



Sheet
S100

Status
Open

Created
Dec 14, 2017 at 3:49pm
mfaenza@crec.org

Last Updated
Dec 14, 2017 at 3:49pm

Description


Optoliner and panel liner has been installed.

Photos



Dec 14, 2017 at 3:49pm

#181 December 14th



Sheet
S100

Status
Open


Created
Dec 14, 2017 at 3:49pm
mfaenza@crec.org

Last Updated
Dec 14, 2017 at 3:50pm

Description

Optoliner and panel liner had been installed.


Photos



Dec 14, 2017 at 3:50pm

North Stonington Emergency Services Building

#182 December 14th



Sheet
S100

Status
Open

Created
Dec 14, 2017 at 3:50pm
mfaenza@crec.org

Last Updated
Dec 14, 2017 at 3:52pm

Description


Block and mortar for cmu wall has been delivered.

Photos



Dec 14, 2017 at 3:51pm

#183 December 19th



Sheet
S100

Status
Open

Created
Dec 19, 2017 at 1:30pm
mfaenza@crec.org

Last Updated
Dec 19, 2017 at 1:32pm

Description


Concrete infills have been formed.
Galvanize door nosing angles have
been set.

Photos



Dec 19, 2017 at 1:31pm

#184 December 19th



Sheet
A1.0

Status
Open

Created
Dec 19, 2017 at 1:33pm
mfaenza@crec.org

Last Updated
Dec 19, 2017 at 1:33pm

Description


Masonry wall installation in progress.

Photos



Dec 19, 2017 at 1:33pm

#185 December 19th



Sheet
A1.0

Status
Open

Created
Dec 19, 2017 at 1:33pm
mfaenza@crec.org

Last Updated
Dec 19, 2017 at 1:34pm

Description


Door frames have been set for installation in masonry wall.

Photos



Dec 19, 2017 at 1:33pm

#186 December 19th



Sheet
A1.0

Status
Open

Created
Dec 19, 2017 at 1:34pm
mfaenza@crec.org

Last Updated
Dec 19, 2017 at 1:34pm

Description


Interior metal framing in progress.

Photos



Dec 19, 2017 at 1:34pm

#187 December 19th



Sheet
M001

Status
Open

Created
Dec 19, 2017 at 1:35pm
mfaenza@crec.org

Last Updated
Dec 26, 2017 at 10:26am

Description

Hangars for HVAC ductwork installation in progress in Admin area.


Photos



Dec 19, 2017 at 1:35pm

North Stonington Emergency Services Building

#189 December 21st



Sheet
C3

Status
Open

Created
Dec 21, 2017 at 8:59am
mfaenza@crec.org

Last Updated
Dec 21, 2017 at 9:00am

Description

Deacon tank has been placed in ground and is being backfilled.


Photos



Dec 21, 2017 at 9:00am

North Stonington Emergency Services Building

#191 December 22nd



Sheet
A1.0

Status
Open

Created
Dec 22, 2017 at 2:37pm
mfaenza@crec.org

Last Updated
Dec 22, 2017 at 2:38pm

Description


Metal wall panel installation in progress.

Photos



Dec 22, 2017 at 2:37pm

#192 December 22nd



Sheet
A1.0

Status
Open

Created
Dec 22, 2017 at 2:38pm
mfaenza@crec.org

Last Updated
Dec 22, 2017 at 2:42pm

Description

Masonry wall installation has been completed.


Photos



Dec 22, 2017 at 2:38pm

North Stonington Emergency Services Building

#193 December 22nd



Sheet
C3

Status
Open

Created
Dec 22, 2017 at 2:42pm
mfaenza@crec.org

Last Updated
Dec 22, 2017 at 2:43pm

Description

Tower base installation in progress.

Photos



Dec 22, 2017 at 2:43pm

North Stonington Emergency Services Building
