

North Stonington Center for Emergency Services - Field Report #21 - 12-25 - 1-5-17

Prepared by Michael Faenza

Description

This field report contains observations from site activities performed during the week of December 29, 2017 and January 5, 2018.

The purpose of this report is to document the progress of the project.

Subcontractors working on site these weeks:

- Xenelis Construction - Pre-Engineered Building
- MCM Acoustics LLC - Framing & Drywall
- Depco Mechanical - HVAC
- CE Electric - Electrical
- Main Enterprises - Plumbing

Key Activities this week include:

- Installation of Building Wall Panels - In Progress
- Interior Metal Framing Installation for Mechanical Mezzanine - In Progress
- Installation of Interior Metal Framing - In Progress
- Installation of Hangars for HVAC Ductwork in Admin Area - In Progress


Please see individual photos and locations within the report for specific detail of activities performed.

Contents

#194 December 29th	2
#195 December 29th	3
#196 December 29th	4
#197 January 3rd	5
#198 January 3rd	6
#199 January 3rd	7

North Stonington Emergency Services Building

#194 December 29th



Sheet
A1.0

Status
Open

Assignees

Created
Dec 29, 2017 at 1:14pm
mfaenza@crec.org

Last Updated
Dec 29, 2017 at 1:15pm

Description


Metal panel installation in progress.

Photos



Dec 29, 2017 at 1:14pm

#195 December 29th



Sheet
M001

Status
Open

Assignees


Created
Dec 29, 2017 at 1:15pm
mfaenza@crec.org

Last Updated
Dec 29, 2017 at 1:16pm

Description


Installation in progress on hangars for ductwork.

Photos



Dec 29, 2017 at 1:15pm

#196 December 29th



Sheet
S101

Status
Open

Assignees

Created
Dec 29, 2017 at 1:16pm
mfaenza@crec.org

Last Updated
Jan 11, 2018 at 1:43pm

Description


Framing in progress at Mezanine.

Photos



Dec 29, 2017 at 1:16pm

#197 January 3rd



Sheet
A1.0

Status
Open

Assignees

Created
Jan 3, 2018 at 3:13pm
mfaenza@crec.org

Last Updated
Jan 3, 2018 at 3:14pm

Description


Metal track for wall framing is being installed on the floor.

Photos



Jan 3, 2018 at 3:13pm

#198 January 3rd



Sheet
M001

Status
Open

Assignees

Created
Jan 3, 2018 at 3:14pm
mfaenza@crec.org

Last Updated
Jan 3, 2018 at 3:15pm

Description


Hangar installation in progress for ductwork in admin area.

Photos



Jan 3, 2018 at 3:14pm

#199 January 3rd



Sheet
A1.0

Status
Open

Assignees

Created
Jan 3, 2018 at 3:15pm
mfaenza@crec.org

Last Updated
Jan 3, 2018 at 3:16pm

Description

Metal panel installation in progress on apparatus bay.

Photos



Jan 3, 2018 at 3:16pm

North Stonington Emergency Services Building
