

North Stonington Center for Emergency Services - Field Report #23 - 1-15-18 - 1-19-18

Prepared by Michael Faenza

Description

This field report contains observations from site activities performed during the week of January 19, 2018.

The purpose of this report is to document the progress of the project.

Subcontractors working on site this week:

Xenelis Construction - Pre-Engineered Building

MCM Acoustics LLC - Framing & Drywall

Depco Mechanical - HVAC

CE Electric - Electrical

Main Enterprises - Plumbing

Key Activities this week include:

Installation of Building Roof System - In Progress

Interior Metal Framing Installation - In Progress

Installation of Interior Door Frames - In Progress

Installation of Hangars for HVAC Ductwork, Fire Protection, Lighting and Plumbing in Admin Area - In Progress

Installation of Gas Piping - In Progress

Installation of Electrical Boxes and Conduit for Power, and Fire Alarm - In Progress

Please see individual photos and locations within the report for specific detail of activities performed.


Contents

#212 January 17th	3
#213 January 17th	4
#214 January 17th	5
#215 January 17th	6
#216 January 17th	7
#217 January 17th	8
#218 January 19th	9
#219 January 19th	10

North Stonington Emergency Services Building

#220 January 19th	11
#221 January 19th	12

#212 January 17th



Sheet
A1.0

Status
Open

Assignees


Created
Jan 17, 2018 at 2:46pm
mfaenza@crec.org

Last Updated
Jan 17, 2018 at 2:46pm

Description


Exterior wall framing is complete in bunk room area.

Photos



Jan 17, 2018 at 2:46pm

#213 January 17th



Sheet
A1.0

Status
Open

Assignees

Created
Jan 17, 2018 at 2:46pm
mfaenza@crec.org

Last Updated
Jan 17, 2018 at 2:47pm

Description


Exterior wall framing is complete at meeting room and office areas.

Photos



Jan 17, 2018 at 2:47pm

#214 January 17th



Sheet
P101

Status
Open

Assignees

Created
Jan 17, 2018 at 2:48pm
mfaenza@crec.org

Last Updated
Jan 17, 2018 at 2:48pm

Description


Gas piping has been brought from meter in to the building and up the wall.

Photos



Jan 17, 2018 at 2:48pm

#215 January 17th



Sheet
P101

Status
Open

Assignees

Created
Jan 17, 2018 at 2:49pm
mfaenza@crec.org

Last Updated
Jan 17, 2018 at 2:49pm

Description


Gas piping has been piped into apparatus bay.

Photos



Jan 17, 2018 at 2:49pm

#216 January 17th



Sheet
E201

Status
Open

Assignees

Created
Jan 17, 2018 at 2:51 pm
mfaenza@crec.org

Last Updated
Jan 17, 2018 at 2:51 pm

Description


Fire alarm boxes are being installed.

Photos



Jan 17, 2018 at 2:51 pm

#217 January 17th



Sheet
E201

Status
Open

Assignees

Created
Jan 17, 2018 at 2:51pm
mfaenza@crec.org

Last Updated
Jan 19, 2018 at 2:26pm

Description


Electrical boxes are being installed.

Photos



Jan 17, 2018 at 2:52pm

#218 January 19th



Sheet
E201

Status
Open

Assignees

Created
Jan 19, 2018 at 2:27pm
mfaenza@crec.org

Last Updated
Jan 19, 2018 at 2:28pm

Description


Conduit extensions have been installed at electrical boxes.

Photos



Jan 19, 2018 at 2:28pm

#219 January 19th



Sheet
A1.0

Status
Open

Assignees

Created
Jan 19, 2018 at 2:28pm
mfaenza@crec.org

Last Updated
Jan 19, 2018 at 2:31pm

Description

Door frames have been installed in bunk room wall.


Photos



Jan 19, 2018 at 2:29pm

North Stonington Emergency Services Building

#220 January 19th



Sheet
S102

Status
Open

Assignees

Created
Jan 19, 2018 at 3:37pm
mfaenza@crec.org

Last Updated
Jan 19, 2018 at 3:39pm

Description


Roofing installation in progress.

Photos



Jan 19, 2018 at 3:37pm

#221 January 19th



Sheet
E201

Status
Open

Assignees

Created
Jan 19, 2018 at 3:39pm
mfaenza@crec.org

Last Updated
Jan 23, 2018 at 1:48pm

Description

Conduit installation in progress for fire alarm.

Photos



Jan 19, 2018 at 3:40pm

North Stonington Emergency Services Building
