

North Stonington Center for Emergency Services - Field Report #6 - 9-4-17 - 9-8-17

Prepared by Michael Faenza

Description

This field report contains observations from site activities performed during the week of September 8, 2017.

The purpose of this report is to document the progress of the project.

Subcontractors working on site this week:

Suchocki & Son Inc. - Sitework

Black Dog Concrete - Concrete

Key Activities this week include:

Installation of Concrete Foundation Wall Forms and Placement of Concrete - In Progress


Excavation and Installation for Wet Well - In Progress

Please see individual photos and locations within the report for specific detail of activities performed.

Contents

#39 September 6th	2
#40 September 6th	3
#41 September 6th	4
#42 September 7th	4
#43 September 7th	5
#44 September 7th	6

#39 September 6th



Sheet
S100

Status
Open

Created
Sep 6, 2017 at 10:23am
mfaenza@crec.org

Last Updated
Sep 6, 2017 at 10:23am

Description

Concrete footings have been formed, poured, and striped.

Photos




Sep 6, 2017 at 10:23am



Sep 6, 2017 at 10:23am

#40 September 6th



Sheet
C2

Status
Open

Created
Sep 6, 2017 at 10:24am
mfaenza@crec.org

Last Updated
Sep 6, 2017 at 10:25am

Description


Wet well pit is being backfilled in lifts and compacted.

Photos



Sep 6, 2017 at 10:25am

#41 September 6th



Sheet
S100

Status
Open

Created
Sep 6, 2017 at 10:26am
mfaenza@crec.org

Last Updated
Sep 7, 2017 at 8:44am

Description


Formwork for foundation walls is being installed.

Photos



Sep 6, 2017 at 10:26am

#42 September 7th



Sheet
C2

Status
Open

Created
Sep 7, 2017 at 8:44am
mfaenza@crec.org

Last Updated
Sep 7, 2017 at 11:06am

Description

Excavation for wet well being back-filled in lifts.


North Stonington Emergency Services Building

Photos



Sep 7, 2017 at 8:44am

#43 September 7th



Sheet
S100

Status
Open

Created

Sep 7, 2017 at 11:06am
mfaenza@crec.org

Last Updated

Sep 11, 2017 at 10:18am

Description


Concrete Foundation wall is being placed.

Photos



Sep 7, 2017 at 11:07am

#44 September 7th



Sheet
S100

Status
Open

Created
Sep 7, 2017 at 11:38am
mfaenza@crec.org

Last Updated
Sep 7, 2017 at 11:38am

Description

Concrete foundation wall is being poured.

Photos



Sep 7, 2017 at 11:38am