

North Stonington Center for Emergency Services - Field Report #7 - 9-11-17 - 9-15-17

Prepared by Michael Faenza

Description

This field report contains observations from site activities performed during the week of September 15, 2017.

The purpose of this report is to document the progress of the project.

Subcontractors working on site this week:

Suchocki & Son Inc. - Sitework

Black Dog Concrete - Concrete

Key Activities this week include:

Installation of Concrete Footings Grade Beams and Placement of Concrete - In Progress

Installation of Storm Water Management System - In Progress


Installation of Piping between Catch Basins - In Progress

Please see individual photos and locations within the report for specific detail of activities performed.

Contents

| | |
|------------------------------|---|
| #45 September 12th | 2 |
| #46 September 12th | 2 |
| #47 September 12th | 3 |
| #48 September 12th | 4 |
| #49 September 13th | 5 |
| #50 September 15th | 6 |
| #51 September 15th | 7 |
| #52 September 15th | 8 |

#45 September 12th



Sheet S100

Status Open

Created Sep 12, 2017 at 11:56am mfaenza@crec.org

Last Updated Sep 12, 2017 at 11:57am

Description


Grade beam has been formed, poured and stripped.

Photos



Sep 12, 2017 at 11:57am

#46 September 12th



Sheet S100

Status Open

Created Sep 12, 2017 at 11:57am mfaenza@crec.org

Last Updated Sep 12, 2017 at 12:56pm

Description

Concrete footing has been formed and rebar has been installed.


North Stonington Emergency Services Building

Photos



Sep 12, 2017 at 11:58am

#47 September 12th



Sheet
C3

Status
Open

Created
Sep 12, 2017 at 12:57pm
mfaenza@crec.org

Last Updated
Sep 12, 2017 at 1:16pm

Description

Piping between CB-6 and CB-4 is being installed.


North Stonington Emergency Services Building

Photos



Sep 12, 2017 at 12:57pm

#48 September 12th



Sheet
S100

Status
Open

Created

Sep 12, 2017 at 1:17pm
mfaenza@crec.org

Last Updated

Sep 12, 2017 at 1:17pm

Description

Concrete is being poured for concrete footing.


North Stonington Emergency Services Building

Photos



Sep 12, 2017 at 1:17pm

#49 September 13th



Sheet
S100

Status
Open

Created
Sep 13, 2017 at 3:47pm
mfaenza@crec.org

Last Updated
Sep 13, 2017 at 3:51pm

Description

Concrete footings have been formed and rebar installation is in progress.


North Stonington Emergency Services Building

Photos



Sep 13, 2017 at 3:48pm

#50 September 15th



Sheet
C3

Status
Open

Created
Sep 15, 2017 at 10:41am
mfaenza@crec.org

Last Updated
Sep 15, 2017 at 10:41am

Description


Stormwater management system installation in progress.

Photos



Sep 15, 2017 at 10:41am

#51 September 15th



Sheet
S100

Status
Open

Created
Sep 15, 2017 at 1:56pm
mfaenza@crec.org

Last Updated
Sep 15, 2017 at 2:58pm

Description

Tie beam has been formed and re-bar has been installed.


North Stonington Emergency Services Building

Photos



Sep 15, 2017 at 1:56pm

#52 September 15th



Sheet
S100

Status
Open

Created
Sep 15, 2017 at 2:14pm
mfaenza@crec.org

Last Updated
Sep 15, 2017 at 2:14pm

Description

Tie beam is being poured with concrete.

Photos



Sep 15, 2017 at 2:14pm