

North Stonington Center for Emergency Services - Field Report #2 - 8-4-17 - 8-11-17

Prepared by Michael Faenza

Description

This field report contains observations from site activities performed during the week of August 4, 2017 and August 11, 2017.

The purpose of this report is to document the progress of the project.

Subcontractors working on site this week:
Suchocki & Son Inc. - Sitework

Key Activities this week include:

Surveying and Layout of Site - In Progress

Site Grading - In Progress

Excavation & Compaction of Building Footings - In Progress

Installation of Water Line Stub & Fire Hydrant on project site - Complete (This work was completed by others as part of the Village Waterline Extension Project.)


Please see individual photos and locations within the report for specific detail of activities performed.

Contents

#16 August 10th	2
#15 August 10th	2
#14 August 10th	3
#13 August 10th	4
#12 August 2nd	5
#11 August 2nd	6

North Stonington Emergency Services Building

#16 August 10th



Sheet
C3

Status
Open

Created
Aug 10, 2017 at 3:25pm
mfaenza@crec.org

Last Updated
Aug 10, 2017 at 3:25pm

Description


Grading in progress.

Photos



Aug 10, 2017 at 3:25pm

#15 August 10th



Sheet
C3

Status
Open

Created
Aug 10, 2017 at 3:24pm
mfaenza@crec.org

Last Updated
Aug 10, 2017 at 3:25pm

Description


Catch basin layout has been completed.

Photos



Aug 10, 2017 at 3:24pm

#14 August 10th



Sheet
C1

Status
Open

Created
Aug 10, 2017 at 3:17pm
mfaenza@crec.org

Last Updated
Aug 10, 2017 at 3:23pm

Description

Waterline has been stubbed on to property and new fire hydrant installed.

Photos




Aug 10, 2017 at 3:20pm



Aug 10, 2017 at 3:21pm

#13 August 10th



Sheet C1

Status Open

Created Aug 10, 2017 at 2:45pm
mfaenza@crec.org

Last Updated Aug 10, 2017 at 3:18pm

Description

Footing excavations have been compacted.


North Stonington Emergency Services Building

Photos



Aug 10, 2017 at 2:45pm

#12 August 2nd



Sheet
C1

Status
Open

Created
Aug 2, 2017 at 9:52am
mfaenza@crec.org

Last Updated
Aug 11, 2017 at 2:23pm

Description

Cutting of site to grade is in progress.


North Stonington Emergency Services Building

Photos



Aug 2, 2017 at 9:53am

#11 August 2nd



Sheet
C1

Status
Open

Created
Aug 2, 2017 at 9:51am
mfaenza@crec.org

Last Updated
Aug 2, 2017 at 9:52am

Description

Excavation for building footings in this area has been completed and compacted.

Photos



Aug 2, 2017 at 9:51am