

North Stonington Center for Emergency Services - Field Report #3 - 8-14-17 - 8-18-17

Prepared by Michael Faenza

Description

This field report contains observations from site activities performed during the week of August 18, 2017.

The purpose of this report is to document the progress of the project.

Subcontractors working on site this week:

Suchocki & Son Inc. - Sitework

Black Dog Concrete - Concrete

Key Activities this week include:

Installation of Formwork for Concrete Footings - In Progress

Excavation for Wet Well - In Progress


Delivery of Drainage Piping and Drainage Structures - In Progress

Please see individual photos and locations within the report for specific detail of activities performed.

Contents

#22 August 18th	2
#21 August 18th	3
#20 August 18th	4
#19 August 18th	5
#18 August 18th	5
#17 August 14th	6

#22 August 18th



Sheet
S100

Status
Open

Created
Aug 18, 2017 at 3:15pm
mfaenza@crec.org

Last Updated
Aug 18, 2017 at 4:16pm

Description


Formwork in progress for concrete footings.

Photos



Aug 18, 2017 at 3:16pm

#21 August 18th



Sheet
C3

Status
Open

Created
Aug 18, 2017 at 3:13pm
mfaenza@crec.org

Last Updated
Aug 18, 2017 at 4:16pm

Description


Concrete drainage structures have begun to arrive on site.

Photos



Aug 18, 2017 at 3:14pm

#20 August 18th



Sheet
S100

Status
Open

Created
Aug 18, 2017 at 3:12pm
mfaenza@crec.org

Last Updated
Aug 18, 2017 at 4:16pm

Description


Formwork for concrete footings in progress.

Photos



Aug 18, 2017 at 3:12pm

#19 August 18th



Sheet
S100

Status
Open

Created
Aug 18, 2017 at 3:10pm
mfaenza@crec.org

Last Updated
Aug 18, 2017 at 4:16pm

Description


Formwork for concrete footings is in progress.

Photos



Aug 18, 2017 at 3:11pm

#18 August 18th



Sheet
C2

Status
Open

Created
Aug 18, 2017 at 3:08pm
mfaenza@crec.org

Last Updated
Aug 18, 2017 at 4:16pm

Description

Excavation in progress for wet well.


North Stonington Emergency Services Building

Photos



Aug 18, 2017 at 3:09pm

#17 August 14th



Sheet
C1

Status
Open

Created
Aug 14, 2017 at 12:45pm
mfaenza@crec.org

Last Updated
Aug 14, 2017 at 12:45pm

Description

Drainage piping has been delivered.

Photos



Aug 14, 2017 at 12:45pm