

North Stonington Center for Emergency Services - Field Report #4 - 8-21-17 - 8-25-17

Prepared by Michael Faenza

Description

This field report contains observations from site activities performed during the week of August 25, 2017.

The purpose of this report is to document the progress of the project.

Subcontractors working on site this week:

Suchocki & Son Inc. - Sitework

Black Dog Concrete - Concrete

Key Activities this week include:

Installation of Formwork for Concrete Footings - In Progress

Excavation for Stormwater Management System - Complete

Installation of Catch Basin Structures - See detail for completed installations


Please see individual photos and locations within the report for specific detail of activities performed.

Contents

#23 August 21st	2
#24 August 21st	2
#25 August 25th	3
#26 August 25th	4
#27 August 25th	5
#28 August 25th	6
#29 August 25th	7

North Stonington Emergency Services Building

#23 August 21st



Sheet
C3

Status
Open

Created
Aug 21, 2017 at 12:39pm
mfaenza@crec.org

Last Updated
Aug 25, 2017 at 1:14pm

Description


Catch basin CB-4 has been set.

Photos



Aug 21, 2017 at 12:40pm

#24 August 21st



Sheet
C3

Status
Open

Created
Aug 21, 2017 at 2:24pm
mfaenza@crec.org

Last Updated
Aug 25, 2017 at 1:13pm

Description

Catch basin CB-6 has been set.


North Stonington Emergency Services Building

Photos



Aug 21, 2017 at 2:25pm

#25 August 25th



Sheet
C3

Status
Open

Created
Aug 25, 2017 at 1:00pm
mfaenza@crec.org

Last Updated
Aug 25, 2017 at 1:01pm

Description

Storm water management system components have been delivered.

Photos




Aug 25, 2017 at 1:01pm



Aug 25, 2017 at 1:01pm

#26 August 25th



Sheet
C3

Status
Open

Created
Aug 25, 2017 at 1:02pm
mfaenza@crec.org

Last Updated
Aug 25, 2017 at 1:03pm

Description


Catch basin CB-8 has been installed.

Photos



Aug 25, 2017 at 1:03pm

#27 August 25th



Sheet
S100

Status
Open

Created
Aug 25, 2017 at 1:04pm
mfaenza@crec.org

Last Updated
Aug 25, 2017 at 1:05pm

Description


Formwork for building footings in progress.

Photos



Aug 25, 2017 at 1:04pm

#28 August 25th



Sheet
C3

Status
Open

Created
Aug 25, 2017 at 1:05pm
mfaenza@crec.org

Last Updated
Aug 25, 2017 at 1:06pm

Description

Excavation has been completed for storm water management system.


North Stonington Emergency Services Building

Photos



Aug 25, 2017 at 1:06pm

#29 August 25th



Sheet
C3

Status
Open

Created
Aug 25, 2017 at 1:08pm
mfaenza@crec.org

Last Updated
Aug 25, 2017 at 1:08pm

Description

Catch basin CB-7 has been installed.

Photos



Aug 25, 2017 at 1:08pm